
| (i) | INSPECTING ENGINEER: J. Mark | TY: Georgia Power Company 5, 2024 on Thomas (Georgia P.E. Licens OF THE IMPOUNDING | | (CCR) | | | | | |
|-------|--|---|---|-----------------------------------|--|--|--|--|--|
| (i) | INSPECTION DATE: November 6 INSPECTING ENGINEER: J. Mark ANY CHANGES IN GEOMETRY C STRUCTURE SINCE THE PREVIOUS | 5, 2024 on Thomas (Georgia P.E. Licens OF THE IMPOUNDING | se #040073) | | | | | | |
| (i) | INSPECTING ENGINEER: J. Mark ANY CHANGES IN GEOMETRY C STRUCTURE SINCE THE PREVIOUS | on Thomas (Georgia P.E. Licens OF THE IMPOUNDING | se #040073) | | | | | | |
| (i) | ANY CHANGES IN GEOMETRY C STRUCTURE SINCE THE PREVIO | OF THE IMPOUNDING | se #040073) | INSPECTION DATE: November 6, 2024 | | | | | |
| (i) | STRUCTURE SINCE THE PREVIO | | | | | | | | |
| | (IF YES, DESCRIBE): | ANY CHANGES IN GEOMETRY OF THE IMPOUNDING STRUCTURE SINCE THE PREVIOUS ANNUAL INSPECTION? | | No ⁽¹⁾ | | | | | |
| , | | | | | | | | | |
| (ii) | LOCATION AND TYPE OF EXIST | See Attached Plan | | | | | | | |
| (ii) | MAXIMUM RECORDED READIN SINCE PREVIOUS ANNUAL INSP | | See Attached Table | | | | | | |
| (iii) | APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF THE IMPOUNDED WATER SINCE PREVIOUS ANNUAL INSPECTION | | | | | | | | |
| | MIN. DEPTH: 0 ft N | 1AX. DEPTH: 36 ft | PRESENT DEPTH: | 32.5 ft | | | | | |
| | MIN. ELEVATION: N/A | IAX. ELEVATION: 723 ft | PRESENT ELEVATION: 719.5 ft | | | | | | |
| (iii) | APPROXIMATE MINIMUM, MAXIMUM AND PRESENT DEPTH AND ELEVATION OF CCR SINCE PREVIOUS ANNUAL INSPECTION | | | | | | | | |
| | MIN. DEPTH: 0 ft M | IAX. DEPTH: 0 ft | PRESENT DEPTH: 0 ft | | | | | | |
| | MIN. ELEVATION: N/A | IAX. ELEVATION: N/A | PRESENT ELEVATION: N/A | | | | | | |
| (iv) | APPROXIMATE STORAGE CAPA STRUCTURE AT TIME OF INSPEC | | 1,413,000 yd ^{3 (2)} | | | | | | |
| (v) | APPROXIMATE VOLUME OF IM AT TIME OF INSPECTION | POUNDED WATER AND CCR | WATER: 1,019,000 yd ³ | CCR: 0 yd ³ | | | | | |
| (vi) | ANY APPEARANCE OF AN ACTUAL OR POTENTIAL STRUCTURAL WEAKNESS OF THE CCR UNIT, IN ADDITION TO ANY EXISTING CONDITIONS THAT ARE DISRUPTING OR HAVE THE POTENTIAL TO DISRUPT THE OPERATION AND SAFETY OF THE CCR UNIT AND APPURTENANT STRUCTURES? | | No | | | | | | |
| | (IF YES, DESCRIBE): | | | | | | | | |
| (vii) | ANY OTHER CHANGE(S) WHICH MAY HAVE AFFECTED THE STABILITY OR OPERATION SINCE THE PREVIOUS ANNUAL INSPECTION? | | No | | | | | | |
| | (IF YES, DESCRIBE): | | <u> </u> | | | | | | |

- (1) This embankment was placed in operation on August 1, 2022, permanently separating AP-2 into an East and West section. All CCR has been removed from both East and West sections. The western portion of AP-2 can no longer impound water. Initial filling of the new Service Water Pond in the eastern section of AP-2 was completed in March 2024.
- (2) Storage volume is taken from crest of labyrinth spillway, El 724.3 ft, based on the stage storage curve updated November 18, 2024.



INSTRUMENTATION PLAN PLANT YATES ASH POND 2



LOCATION, TYPE, & MAXIMUM RECORDED READINGS OF INSTRUMENTATION YATES ASH POND 2

| Instrument No | Type of Instrument | Location of Instrument | | Maximum Elevation Since |
|----------------|--------------------|------------------------|---------|-------------------------|
| Instrument No. | | Northing | Easting | Last Inspection |
| P-1 | Piezometer | 1259537 | 2070931 | 709 |
| P-2 | Piezometer | 1259327 | 2071004 | 705 |
| P-3 | Piezometer | 1259298 | 2070955 | 701 |
| P-4 | Piezometer | 1259284 | 2070931 | 701 |
| P-5 | Piezometer | 1259196 | 2071115 | 707 |
| P-6 | Piezometer | 1259153 | 2071078 | 702 |
| P-7 | Piezometer | 1259129 | 2071060 | 701 |
| P-8 | Piezometer | 1259103 | 2071273 | 716 |